Sensor Standards Harmonization (SSHWG) Working Group Meeting

Date: April 30, 2008 Time: 9:30 a.m. to 4:00 p.m.

Location: NIST Administration Bldg 101, Lecture Room B

Agenda:

0930	Welcome & Self-Introduction of Participants
0940	Summary of Previous SSHWG meetings – Kang Lee, NIST
1000	DHS SBInet Sensor System Overview and Standards Requirements - Rama Suresh, DHS CBP SBInet System Program Office
1030	SensorPedia Update – Bryan Gorman, ORNL
1100	Break for coffee and networking
1120	Integration of OGC SWE and IEEE 1451 sensors using Smart Transducer Web Services, with demonstration – John Davidson and 1451 Team
12:00	Lunch break and networking
1300	Sensor standards need for plume detectors – Hamilton Hunter, ORNL
1330	A simple view of Plug-and-Play of IEEE 1451 sensor module, with demonstration - Jon Geist, NIST
1400	IEEE 1451 Deployment and Conformance Testing Considerations – Darold Wobschall, Esensor and Deniz Gurkan, University of Houston
1430	Discussion: - Plugfest at SAS – Deniz Gurkan, University of Houston - Semantic Sensor Web Undate

- Semantic Sensor Web Update
- Other related standards and activities
- 1600 Meeting adjournment

IEEE 1451 Deployment and Conformance Testing Considerations

Registration

This meeting is held as one of the activities of the NIST Interoperability Week. Thus you are required to register for this meeting to get a NIST pass. Please check out the web link and register online. There is no registration cost for this meeting.

The NIST Interoperability Week website with session description is up. The URL is: http://www.mel.nist.gov/div826/msid/sima/interopweek/meetings.htm

Registration for the Sensor Standards Harmonization Working Group meeting can also be access through the following URL link.

http://www.nist.gov/public_affairs/confpage/080430.htm

If I can be of further assistance, please contact me.

Regards,

Kang Lee

Tel: 301-975-6604

Email: kang.lee@nist.gov

Hotels and transportation information:

Hotels near NIST can be found at http://www.nist.gov/public_affairs/visitor/visitor.htm

Direction to NIST Admin Building 101, Lecture Room D:

From Rt 495 (Beltway), take Rt 270 north to Gaithersburg.

On Rt 270, after the Shady Grove Exit, start looking for exit 10 and move from the Rt 270 high-speed lanes to the local lanes.

Take exit 10, or Rt 117 Clopper Road (NIST) exit.

Keep right and take a right at the light and follow the road bearing left for about 1/4 mile. At the next light is Bureau Drive and the NIST front entrance is on your left.

At the entrance, tell the guard you have been registered and need to pick up a visitor badge. The guard will direct you to the visitor center.

After you leave the visitor center, drive to the STOP sign and turn left on North Drive.

Follow the road to the next intersection and turn left and immediate right into the parking lot on your right.

Park your car and walk toward the front entrance of the 11-story Admin Building 101.

After entering the building, go straight and pass the elevators, turn left and Lecture Room D is the first room on your left.